Panel Meter Model PM6-TR Operation and Instruction Manual

AMALGAMATED INSTRUMENT COABN: 80 619 963 692Unit 5, 28 Leighton Place Hornsby
NSW 2077 AustraliaTelephone: +61 2 9476 2244
Facsimile: +61 2 9476 2902e-mail: sales@aicpl.com.au
Internet: www.aicpl.com.au

Table of Contents

1	Introduction	3
2	Mechanical Installation	4
3	Electrical installation	5
4	Function tables - summary of setup functions	13
5	Explanation of functions	15
6	Specifications	29
7	Guarantee and service	30

1 Introduction

1.1 General description

This manual contains installation and operation information for model PM6-TR monitor. Model PM6-TR can be set to display rate/frequency or total from pulse inputs. The displayed output may be scaled to read in engineering units to suit the application. A remote switch can be used to toggle between rate and total display if required. The default display can be set to show rate or total, see dF; E d; SP function on page 20.

The rate display is scaled using the $\neg R \models E \land \neg P \models$ and $\neg R \models E S \subseteq E$ functions. The total is scaled using the $\flat o \models i \land \neg P \models$ and $\flat o \models i \land \neg P \models i \land \neg P \models$ and $\flat o \models i \land \neg P \models i \land \neg P$

Unless otherwise specified at the time of order your PM6-TR has been factory set to a standard configuration. This configuration can be easily changed by the user. All changes to configuration and scaling are made via three push buttons located at the rear of the unit, see chapter 5, page 15. Chapter 5 details all of the setup functions, read this chapter and record your settings for each function in the space provided in the function tables, chapter 4 starting on page 13.

Functions Lo FrE9 and H; 9H FrE9 and Lo LoL; and H; 9H LoL; allow visual warnings of under or over rate/frequency or total by either flashing the display value on or off or showing the error message -or -.

The PM6 series instruments are designed for high reliability in industrial applications. The display can be set to switch brightness between two levels via an external switch for day/night level switching etc. The PM6 range of instruments are monitor only devices and contain no outputs. Other ranges of instruments are available to suit a wide range of instrumentation needs.

2 Mechanical Installation

Choose a mounting position as far away as possible from sources of electrical noise such as motors, generators, fluorescent lights, high voltage cables/bus bars etc. An IP65 access cover which may be installed on the panel and surrounds is available as an option to be used when mounting the instrument in damp/dusty positions. A wall mount case is available, as an option, for situations in which panel mounting is either not available or not appropriate. A portable carry case is also available, as an option, for panel mount instruments.

Prepare a panel cut out of 45 mm x 92 mm + 1 mm / - 0 mm (see diagram below). Insert the instrument into the cut out from the front of the panel. From the rear of the instrument fit the two mounting brackets into the recess provided (see diagram below). Whilst holding the bracket in place, tighten the securing screws being careful not to over-tighten, as this may damage the instrument. Hint: use the elastic band provided to hold the mounting bracket in place whilst tightening securing screws.



3 Electrical installation

3.1 Electrical installation

The PM6 Panel Meter is designed for continuous operation and no power switch is fitted to the unit. It is recommended that an external switch and fuse be provided to allow the unit to be removed for servicing.

The plug in, screw type, terminal blocks allow for wires of up to 2.5mm² to be fitted. Connect the wires to the appropriate terminals as indicated below. Refer to connection details provided in this chapter to confirm proper selection of voltage, polarity and input type before applying power to the instrument.

When power is applied the instrument will cycle through a display sequence indicating the software version and other status information, this indicates that the instrument is functioning. Acknowl-edgement of correct operation may be obtained by applying an appropriate input to the instrument and observing the reading. The use of screened cable is recommended for signal inputs.



Instrument label (example)

	C N1440					
1	MAINS EARTH					
2	240 VAC NEUTRAL					
3	240 VAC ACTIVE					
5	+24VDC UNREG OUTPUT					
6	GROUND					
7	INPUT					
8	REMOTE INPUT 1					
9	GROUND					
10	REMOTE INPUT 2					
<u>µ11</u>	+5VDC UNREG OUTPUT					
	PM6-TR-240-4E	SERIAL No.: XXXXX-XXX				

3.2 Input connection and internal link settings



Notes: Inputs 100mV to 2.5V HYS2 (LK3) is **In**, HYS1 (LK2) is **Out**. Inputs above 2.5V HYS2 is **Out**, HYS1 is **In**. For inputs above 24V RMS SL- (LK6) is **Out**. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.



Notes: Inputs 100mV to 2.5V HYS2 is **In**, HYS1 is **Out**. Inputs above 2.5V HYS2 is **Out**, HYS1 is **In**. For inputs above 24V RMS SL- is **Out**. DC link LK5 should be **In** if the frequency will not be greater than 10Hz. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.



Notes: Inputs 100mV to 2.5V HYS2 (LK3) is **In**, HYS1 (LK2) is **Out**. Inputs above 2.5V HYS2 is **Out**, HYS1 is **In**. For inputs above 24V SL- (LK6) is **Out**. BIAS link (LK1) should be **In** if the signal does not go below 0V. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.





Notes: The LFRE link (LK4) when In can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.



Notes: The LFRE link (LK4) when In can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.

In

In

Out

Out

In

In

Out



Notes: Use terminal 5 for 24V (20mA max) or terminal 11 for 5V (20mA max) or use external excitation. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.



Notes: Use terminal 5 for 24V (20mA max) or terminal 11 for 5V (20mA max) or use external excitation. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.



Notes: Use terminal 5 for 24V (20mA max) or terminal 11 for 5V (20mA max) or use external excitation. The LFRE link (LK4) when **In** can be used to help filter out high frequency noise and contact bounce provided that the maximum input frequency of the pulse signal is less than 80Hz.

Wiring in cases of high interference

For environments with high electrical noise where interference with the signal input is occurring terminal 1 (mains earth or case earth) can be connected to GND terminals 6 or 9. In many cases this will reduce the interference. Note that this should only be done where the shield is not externally connected.



Remote inputs for totaliser reset etc.

Two remote inputs are provided as shown below. One or both of these can be used and the required operation selected at the Γ . ΠP and Γ . ΠP and Γ . ΠP functions. One of these remote inputs can be used to reset the totaliser. Alternatively the $\Gamma L \Gamma L \sigma L$ function can be used to clear the total. See functions 5.18 and 5.19 for description of remote input functions available. Note that if both remote inputs are used they should be set to different functions e.g. do not set both remote inputs to peak memory operation.



24VDC unregulated DC sensor supply

Connections for the unregulated 24VDC sensor supply are shown below. Note that this supply is only available in AC powered models. If a DC supply is used the output form these terminals will be approximately 12VDC. Maximum current 50mA.



5VDC unregulated DC sensor supply

Connections for the 5VDC unregulated sensor supply are shown below. Maximum current 20mA.



3.3 Input Output Configuration

If you need to alter the input or output configuration link settings proceed as follows:



- 6. Replace the earth screw which passes through the case
- 7. Refit the back cover and fix with the self tapping screws
- 8. Plug the terminal strips back into the rear of the instrument

3.4 Input range link selection

Dismantle the instrument as described in section Insert the links into the appropriate location on the pin header to suit the range required.



4 Function tables - summary of setup functions

Display	Function	Range	Default	Your	Ref/Page
				record	
br 9t	Display brightness level	1 to 15	15		5.1 / 16
dull	Display remote brightness switching	0 to 15	1		5.3 / 17
drnd	Display rounding	1 to 5000	1		5.2 / 16
FLEr	Digital filter	0 to 8	2		5.4 / 17

Functions in this first table are available in $\ensuremath{\textit{Func}}$ or $\ensuremath{\textit{CRL}}$ mode

Functions in this second table are available in $\ensuremath{\textit{CRL}}$ mode only

Display	Function	Range	Default	Your record	Ref/Page
tout	Frequency display timeout seconds	ł to 255	1		5.5 / 17
Fre9 Fn9e	Frequency range	ПОЛЕ, 10, 100 or 5000	ΠΟΠΕ		5.6 / 18
I NPE Ed9E	Input edge	FISE or Fall	ΓI SE		5.7 / 18
rALE d[PL	Frequency/rate display decimal point	0 to 0.003	0		5.8 / 18
r AEE , nPE	Frequency input	; to 9999	1		5.9 / 18
rALE SCLE	Frequency scale	: to 9999	1		5.10 / 19
tot; d[Pt	Total decimal	0 to 0.003	0		5.11 / 19
tot; , nPt	Total input	; to 9999	1		5.12 / 19
tot; SCLE	Total scale	; to 9999	1		5.13 / 19
tot; [RP.F	Total wrap around operation	SEOP or ZEFO	SEOP		5.14 / 20
[Lr tot;	Clear total	n/a	n/a		5.15 / 20
dFIE disp	Default display	rALE or Loti	r AFE		5.16 / 20
c.rSt	Total reset input	Lo, H, , Lo E or H, E	Lo		5.17 / 20

Г.1 ПР	Remote input 1 function	NDNE, P.HLd, d.HLd, H, , Lo, duLL, d; SP or 2Er0	NONE	5.18 / 21
r.; n2	Remote input two (external input) function	NDNE, P.HLd, d.HLd, H, , Lo, duLL, d) SP or 2EFD	NONE	5.19 / 22
Lo FrE9	Low rate visual warning limit value	Any display value or DFF	OFF	5.20 / 22
HI 9H Freq	High frequency/rate visual warning limit value	Any display value or DFF	OFF	5.21 / 22
r ALE d; SP	Rate display visual warning flashing mode	FLSH or For F	FLSH	5.22 / 23
Lo tot;	Low total visual warning limit value	Any display value or DFF	OFF	5.23 / 23
H; 9H Łoł;	High total visual warning limit value	Any display value or DFF	OFF	5.24 / 23
tot; d; SP	Total display visual warning flashing mode	FLSH or	FLSH	5.25 / 23
RCCS	Access mode	OFF.NONE or ALL	OFF	5.26 / 24

5 Explanation of functions

The PM6 setup and calibration/scaling functions are configured through a push button sequence. The three push buttons located at the rear of the instrument are used to alter settings. Two basic access modes are available:

FUNC mode (simple push button sequence) allows access to common set up functions such as display brightness.

CRL mode (power up sequence plus push button sequence) allows access to all functions including calibration/scaling parameters.



Once **CRL** or **FUNC** mode has been entered and the first function is displayed step through the functions by pressing and releasing the \square push button until the required function is reached. For most setup functions the function name is displayed followed by the function setting and the function name will then flash briefly once every 8 seconds as a reminder of the function being viewed. Changes to functions are made by pressing the \square or \square push button (in some cases both simultaneously) when the required function is reached. When the required function has been changed continue pressing and releasing the \square button until the **FUNC End** message is seen and the

display returns to normal measurement display. Changes to function settings will not be saved into memory unless either the **FUNC End** message is reached or if the panel meter has automatically reverted back to normal measurement display. The display will automatically revert back to normal display approximately 5 minutes after **CRL** or **FUNC** mode entry. See the flow chart example of changing a function below.

Example: Entering **CRL** mode to change rate decimal point function $\neg R \vdash E dCP \vdash$ from **O** to **0.02**



5.1 Display brightness

Display:br 9LRange:1 to 15Default Value:15

Displays and sets the digital display brightness. The display brightness is selectable from i to i, where i = lowest intensity and i = highest intensity. This function is useful for improving the display readability in dark areas or to reduce the power consumption of the instrument. See also the **dull** function. To set brightness level go to the **br9t** function and use the **D** or **D** push buttons to set the value required then press **E** to accept this value.

5.2 Display rounding

Display:	drad
Range:	1 to 5000
Default Value:	1

Displays and sets the display rounding value for the rate/frequency display only. This value may be set to 1 - 5000 displayed units. Display rounding is useful for reducing the instrument resolution without loss of accuracy in applications where it is undesirable to display to a fine tolerance. To set the display rounding value go to the dr ad function and use the Δ or \Box push buttons to set the required value then press \Box to accept this selection.

Example:

If set to **10** the rate/frequency display values will change in multiples of 10 only i.e. display moves from **10** to **20** to **30** etc.

5.3 Display remote brightness switching

Display:	dul	L
Range:	D to	15
Default Value:	1	

Displays and sets the level for remote input brightness switching, see Γ . ΠP function 5.18 and Γ . ΠR function 5.19. When a remote input is set to **dull** the remote input can be used to switch between the display brightness level set by the **b** Γ **S** ϵ function 5.1 and the display brightness set by the **dull** function. The display dull level is selectable from Ω to IS, where $\Omega =$ lowest intensity and IS = highest intensity. This function is useful in reducing glare when the display needs to be viewed in both light and dark ambient light levels. To set dull level go to the **dull** function and use the \square or \square push buttons to set the value required then press \square to accept this value.

Example:

With d_{ULL} set to \forall and $b_{r}S_{E}$ set to iS and the r. iP function set to d_{ULL} the display brightness will change from the iS level to \forall when a switch connected to the remote input terminals is activated.

5.4 Digital filter

Display:FLErRange:I to BDefault Value:Z

Displays and sets the digital filter value. Digital filtering uses a weighted average method of determining the display value and is used for reducing display value variation due to short term interference. The digital filter range is selectable from \mathbf{O} to \mathbf{B} , where $\mathbf{O} =$ none and $\mathbf{B} =$ most filtering. Use \square or \square at the FLEr function to alter the filter level if required. Note that the higher the filter setting the longer the display may take to reach its final value when the input is changed. To set the digital filter value go to the FLEr function and use the \square or \square push buttons to set the required value then press \square to accept this selection.

5.5 Frequency display timeout seconds

Display:	Lout
Range:	ł to 255
Default Value:	1

Displays and sets the timeout for the frequency display. If the input period is less than the **Lout** setting the display will flash between the rate and zero or be stuck on zero. To avoid this select a value at this function which is higher than the period of the lowest expected frequency input. For example if the **Lout** setting is set to 10 seconds then the previous rate display will be held for at least 10 seconds and will only revert to a zero display if no new input is seen during this 10 seconds.

5.6 Frequency range

 Display:
 Freqrage

 Range:
 DORE,
 IO,
 IOO or SOOO

 Default Value:
 DORE

Displays and sets maximum input frequency range. This function allows a maximum frequency range to be selected and frequencies higher than this will be rejected i.e. this function can be used to help eliminate false readings due to high frequency noise, contact bounce etc. Note: Internal link LK5 may also be used to help filter out contact bounce and high frequency noise if the signal input frequency is always below 80Hz, see section 3.2. Selections available for the $FrE9 \Gamma n9E$ function are:

NORE - no filtering, accepts inputs up to 10kHz

10 - maximum input frequency of 10Hz

100 - maximum input frequency of 100Hz

 $\ensuremath{\texttt{5000}}$ - maximum input frequency of 5kHz

5.7 Input edge

Display:I MPL EdgeRange:FISE or FALLDefault Value:FISE

Displays and sets the pulse input edge on which triggering will occur. If set to **F: SE** then the rising edge of the input pulse will trigger the input. If set to **FRLL** then the falling edge of the input pulse will trigger the input. This function can be useful if one of the edges provides a better switching input than the other e.g. if there is a long rise time in the pulse input but a sharp fall time then select **FRLL** as this will give a more definite pulse transition.

5.8 Frequency/rate display decimal point

Display:	rREE dEPE
Range:	0 to 0.003
Default Value:	0

Displays and sets the decimal point position for the frequency/rate display. Note if this is altered it may be necessary to alter the $\neg R \models E$ SCLE function also.

5.9 Frequency input scaling factor

Display:	- REE , _PE
Range:	; to 9999
Default Value:	1

Displays and sets the number of input pulses to be used with the **~REE SELE** function to generate the required display scaling, see **~REE SELE** below.

5.10 Frequency scaling factor

Display:	ALE SELE
Range:	; to 9999
Default Value:	1

Displays and sets the scaling factor to be used with the $\neg R \vdash E , \neg P \vdash$ function to generate the required display scaling. The frequency scale factor can be set to any display value and the decimal point value seen at this function will be set by the $\neg R \vdash E d \Box P \vdash$ function. The display value is calculated in the following manner:

 $Rate display = \frac{Input frequency (Hz) \times \textbf{rRtESCLE}}{\textbf{rRtE, oPt}}$

Example: To scale the display to read in RPM to one decimal place from an input which gives 10 pulses per revolution set rRE dCPE to O.1, set rRE rRE rRE rRE to 10 and set the rRE SCLE to SO.O (since the input is measured in pulses per second (Hz) the rRE SCLE is set to SO.O i.e. 60 seconds in one minute).

5.11 Total display decimal point

Display:	tot; d[Pt
Range:	0 to 0.003
Default Value:	0

Displays and sets the decimal point position for the total display. Note if this is altered it may be necessary to alter the **LOE**; **SELE** function also.

5.12 Total input scaling factor

Display:	toti , nPt
Range:	; to 9999
Default Value:	1

Displays and sets the number of input pulses to be used with the **Lot**; **SCLE** function to generate the required display scaling, see **Lot**; **SCLE** below.

5.13 Total scaling factor

Display:	tot;	SELE
Range:	to 🖣	999
Default Value:	1	

Displays and sets the scaling factor to be used with the **LoL**; **IPL** function to generate the required display scaling. The total scale factor can be set to any display value and the decimal point value seen at this function will be set by the **LoL**; **dCPL** function. The display value is calculated in the following manner:

 $Total display = \frac{Input pulses counted \times \texttt{tot}; \texttt{SCLE}}{\texttt{tot}; \texttt{oPt}}$

PM6TRMAN-1.3-0

Example: To scale the display to count total kilolitres with 2 decimal place from an input which gives 1 pulse per litre (i.e. 1,000 pulses per kilolitre) set **Lot**; **dCPL** to **0.02**, set **Lot**; **; nPL** to **1000** and set the **Lot**; **SCLE** to **1.00** (i.e. display will increment by 0.01 kilolitres for every 10 input pulses and by 1.00 kilolitres for every 1000 input pulses).

5.14 Total wrap around operation

Display:	tot; CRP.F
Range:	SEOP or SELO
Default Value:	SEOP

Displays and sets the totaliser wrap around operation for displays at full scale. If **SEOP** is selected the display will halt at **9999** or **999.9** etc. If **ZEFO** is selected then the display will wrap around to zero i.e. will reset itself and start again at zero.

5.15 Clear total

Display:	ELr toti
Range:	n/a
Default Value:	n/a

Allows the totaliser value to be cleared via the setup pushbuttons located at the rear of the instrument. To clear the totaliser press \square and \square simultaneously at this function. The message *L* - *d* will be seen to indicate that the total memory has been cleared resetting the total to zero. See also the remote input functions *F*.: *NP* and *F*.: *RP* and *f* **.: ***RP* and *f*.: *RP* and *f* **.: ***RP* and *f* **.: ***RP* and *f*.: *RP* and *f* **.: ***RP* and *f* .: *RP* and *f* .: *RP* and *f* .: *RP* and *f* .: *RP* and *f*

5.16 Default display

Display:dF: L d: SPRange:rRLE or LoL:Default Value:rRLE

Displays and sets the default display. The default display selected is the one which will always appear on the display after power is applied. Select $\neg R \vdash E$ to have the rate display as the default display. Select $\vdash o \vdash i$ to have the total display set as the default display. The display can also be set to change from the default display via the one of the remote inputs \varGamma . $\sqcap P$ function 5.18 or \varGamma . $\sqcap R \vdash E$ function 5.19 or can be toggled between displays via the \square or \square pushbuttons. When the display is changed to the non default display a message will flash every 8 seconds e.g. $\ulcorner R \vdash E$ to indicate that the alternate display is being viewed.

5.17 Total reset input

Display:	c.rSt
Range:	Lo, H, , LoE or H, E
Default Value:	Lo

Displays and sets the reset input for the total display. Remote input 1 or 2 can be programmed to act as the reset input by setting the Γ ; ΠP or Γ ; $\Pi 2$ function to $2E\Gamma\Omega$. The reset input is held high by an internal 5VDC, this can be pulled to ground via a voltage free contact. The reset input can be set to operate from an input level or and input edge. Settings available are as follows:

- Lo a low level (short circuit to GND) will reset the display (if the level is held low the display will not totalise)
- **H**, a high level (open circuit) will reset the display (if the level is held high the display will not totalise)
- LoE the total will reset on a low going edge transition only
- H, E the total will reset on a high going edge transition only

5.18 Remote input 1 function

Display:F.: NPRange:NONE, P.HLd, d.HLd, H., Lo, dull, di SP or 2ErODefault Value:NONE

Remote input function - terminals 8 and 9 at the rear of the instrument are the remote input 1 terminals. When these terminals are short circuited via a switch, relay, keyswitch etc. the instrument will perform the selected remote input function. For settings other than **ADAE**, **dull** and **ZEFD** a message will flash to indicate which function has been selected when the remote input pins are short circuited. The remote input functions are as follows:

- **NDNE** no remote function required i.e. activating the remote input has no effect.
- **P.HLd** frequency/rate peak hold. The display will show the peak rate value (highest positive value) only whilst the remote input terminals are short circuited i.e. the display value can rise but not fall whilst the input terminals are short circuited. The message **P.HLd** will appear briefly every 8 seconds whilst the input terminals are short circuited to indicate that the peak hold function is active. Note: the peak hold operates on the rate display only, if total is being viewed the display will change to the peak held rate value whilst the remote input is activated.
- **d.HLd** frequency/rate display hold. The rate display value will be held whilst the remote input terminals are short circuited. The message **d.HLd** will appear briefly every 8 seconds whilst the input terminals are short circuited to indicate that the display hold function is active. Note: the display hold operates on the rate display only, if the total is being viewed the display will change to the held value whilst the remote input is activated. Whilst the rate display is held the totaliser will still be active and operating from the live input, not the held value.
- H. frequency/rate peak memory. The peak rate value stored in memory will be displayed if the remote input terminals are short circuited, if the short circuit is momentary then the display will indicate the peak memory value then return to normal measurement after 30 seconds. To reset the memory hold the remote input closed for 2 to 3 seconds or remove power from the instrument. The message P H. will appear briefly every 8 seconds whilst the input terminals are short circuited to indicate that the peak memory function is active. Note: the peak memory operates on the rate display only, if the total is being viewed the display will change to the peak rate memory for 30 seconds after the remote input is activated.
- Lo frequency/rate valley memory. The minimum rate value stored in memory will be displayed. The message P Lo will appear briefly every 8 seconds whilst the input terminals are short circuited to indicate that the peak memory function is active. Otherwise operates in the same manner as the H. function described above. Note: the valley memory operates on the rate display only, if the total is being viewed the display will change to the valley rate memory for 30 seconds after the remote input is activated.

- **dull** display brightness control. The remote input can be used to change the display brightness. When this mode is selected the display brightness can be switched, via the remote input terminals, between the brightness level set at the **br9t** function and the brightness level set at the **dull** function.
- d; 5P change display. The remote input can be used to toggle between the default display (set at the dF: L d; 5P function) and the second display. e.g. if the default display is set to show rate then the remote input will toggle from the rate to the total display when activated.
- **2EFO** zero the total. The remote input can be used to reset the total to zero. The **c.rSt** function sets the level required for reset.

5.19 Remote input 2 function

Display:F.I N2Range:NONE, P.HLd, d.HLd, H, , Lo, dull, di SP or 2EFODefault Value:NONE

Remote input two functions, operates in the same manner as the first remote input but uses terminals 9 and 10. Refer to Γ : ΠP function 5.18 for description. Note: unless set to $\Pi \Omega \Pi E$ it is essential that Γ : ΠP and Γ : ΠR are not set for the same function. If both remote inputs are activated at the same time remote input 1 will take priority.

5.20 Low frequency/rate visual warning limit value

Display:	Lo FrE9
Range:	Any display value or DFF
Default Value:	OFF

Low frequency/rate limit value - the display can be set to show a visual warning if the frequency/rate display value falls below the Lo FrEP setting. For example if Lo FrEP is set to SO then once the display reading falls below SO the message -or - will flash on and off or the display value will flash on and off instead of the normal display units (see rPEEd; SP function 5.22). This message can be used to alert operators to the presence of an input which is below the low limit. If this function is not required it should be set to OFF by pressing the \square and \square buttons simultaneously at this function.

5.21 High rate visual warning limit value

Display:	HI 9H FrE9
Range:	Any display value or \pmb{OFF}
Default Value:	OFF

High frequency/rate limit value - the display can be set to show a visual warning if the rate display value rises above the **H! SHFrE9** setting. For example if **H! SHFrE9** is set to **!OOO** then once the display reading rises above **!OOO** the message **-or -** will flash on and off or the display value will flash on and off instead of the normal display units (see **rREEd! SP** function 5.22). This message can be used to alert operators to the presence of an input which is above the high limit. If this function is not required it should be set to **OFF** by pressing the **\Box** and **\Box** buttons simultaneously at this function.

5.22 Rate display visual warning flashing mode

Display:	r REE di SP
Range:	FLSH or for
Default Value:	FLSH

Rate display overrange warning flashing mode - this function is used in conjunction with the **Lo rALE** and **HI GH rALE** functions. The **rALE dI SP** function can be set to **FLSH** or **-or**. If the value set at the **Lo rALE** or **HI GH rALE** function is exceeded and the **rALE dI SP** function is set to **FLSH** then the display value will continually flash on and off every second as a visual warning. If the value set at the **Lo rALE** or **HI GH rALE** function is exceeded and the **rALE dI SP** function is set to **-or** - then the **-or** - message will continuously flash on and off once a second as a visual warning. The warning flashes will cease and the normal display value will be seen when the value displayed is higher than the low limit and lower than the high limit.

5.23 Low total visual warning limit value

Display:	Lo tot;
Range:	Any display value or OFF
Default Value:	OFF

Low total limit value - the display can be set to show a visual warning if the total display value falls below the **Lotot**; setting. For example if **Lotot**; is set to **SO** then once the display reading falls below **SO** the message **-or** - will flash on and off or the display value will flash on and off instead of the normal display units (see **Lot**; **d**; **SP** function 5.25). This message can be used to alert operators to the presence of an input which is below the low limit. If this function is not required it should be set to **OFF** by pressing the **\Box** and **\Box** buttons simultaneously at this function.

5.24 High total visual warning limit value

Display:	HI 9H EoEl
Range:	Any display value or \pmb{OFF}
Default Value:	OFF

High total limit value - the display can be set to show a visual warning if the total display value rises above the **H! SHLOL!** setting. For example if **H! SHLOL!** is set to **!DDD** then once the display reading rises above **!DDD** the message **-or -** will flash on and off or the display value will flash on and off instead of the normal display units (see **LOL! d! SP** function 5.25). This message can be used to alert operators to the presence of an input which is above the high limit. If this function is not required it should be set to **DFF** by pressing the **\Box** and **\Dox** buttons simultaneously at this function.

5.25 Total display visual warning flashing mode

Display:	tot¦ d¦ SP
Range:	FLSH or -or-
Default Value:	FLSH

Total display overrange warning flashing mode - this function is used in conjunction with the Lo LoL; and HI SH LoL; functions. The LoL; dI SP function can be set to FLSH or -or.

If the value set at the Lo rREE or H: GH rREE function is exceeded and the Lot: d: SP function is set to FLSH then the display value will continually flash on and off every second as a visual warning. If the value set at the Lo Lot: or H: GH Lot: function is exceeded and the Lot: d: SP function is set to -or - then the -or - message will continuously flash on and off once a second as a visual warning. The warning flashes will cease and the normal display value will be seen when the value displayed is higher than the low limit and lower than the high limit.

5.26 Access mode

Display:	REES
Range:	OFF, NONE or ALL
Default Value:	OFF

Access mode - the access mode function **RECS** has three possible settings namely **OFF**.**NONE** and **RLL**. If set to **OFF** the function has no effect. If set to **NONE** there will be no access to any functions via **FUNE** mode, entry via **ERL** mode must be made to gain access to functions. If set to **RLL** then access to all functions, including calibration functions, can be gained via **FUNE** mode i.e. when set to **RLL** there is no need to power down to gain access to all functions.

5.27 Examples

Example - RPM display

A proximity sensor connected to a flywheel produces 20 pulses per revolution. The instrument is required to display in RPM with 1 decimal point place. In this example 20 pulses per second would equal 1 revolution/sec which equals 60 RPM. The **FREE FRE** figure and **FREE SELE** figure could be **20** and **50.0** respectively but we will use **1** and **3.0** since they give the same ratio and hence will give the same reading on the display.

- 1. Follow the procedure shown on page 15 to enter the setup functions via **CRL** mode.
- 2. Step through the functions by pressing and releasing **E** until the **FREE dEPE** function is seen.
- 3. Use the \square or \square push button to change the setting to \square .
- 4. Press **E**, the function **FREE PE** will appear followed by the previous input value.
- 5. Use the \square or \square push button to alter the previous input value to the new input value of \blacktriangleleft .
- 6. Press **E**, the function **FREE SELE** will appear followed by the previous scale value.
- 7. Use the \square or \square push button to alter the previous scale value to the new scale value of **3.9**.
- 8. Press 🖬 to accept the change then either press 🖻 to exit of continue pressing and releasing 🖬 until the FUNC End message is seen and the unit returns to normal measure mode.

Example - Low frequency input rate display

A transducer is being used to give one pulse out for every bottle passing a point on a track. The display is required to show bottles per hour. The number of bottles passing can be as low as one every five seconds up to two per second. The **FREE FOPE** value will be **f** and the **FREE SCLE** value will be **3600** i.e. 1 bottle per second = 3600 bottles per hour. The procedure is as follows:

- 1. Follow the procedure shown on page 15 to enter the setup functions via **CRL** mode.
- 2. Step through the functions by pressing and releasing **I** until the **Louk** function is seen.
- 3. Use the \square or \square push button to change the setting to a value greater than \square seconds e.g. 8.
- 4. Step through the functions by pressing and releasing **E** until the **FREE INPE** function is seen.
- 5. Use the \square or \square push button to change the setting to \blacktriangleleft .
- 6. Press **I**, the function **FREE SCLE** will appear followed by the previous input value.
- 7. Use the \square or \square push button to change the setting to **3600**.
- 8. Press **I** to accept the change then either press **P** to exit of continue pressing and releasing **I** until the **FUNC End** message is seen and the unit returns to normal measure mode.

Example - Flow rate display

See previous examples for detailed steps showing how to alter functions. Flowmeters produce an output frequency proportional to the rate of flow the scaling is calculated using information provided by the manufacturer or from test results. e.g.: A turbine produces 767 pulses per litre

- to display litres/minute set **FRE ; NPE** to **767** and **FREE SELE** to **60**.
- to display litres/hour set **FALE ; MPL** to **767** and **FALE SELE** to **3600**.
- to display kilolitres/hour set **FRE** ; **PPE** to **7670** and **FREE SELE** to **36**.

Example - Flowmeter totalising

A flowmeter produces 56 pulses per litre. The display us required to show total litres with 1 decimal point place. The procedure is as follows.

- 1. Follow the procedure shown on page 15 to enter the setup functions via **CRL** mode.
- 2. Step through the functions by pressing and releasing **E** until the **Lot**: **dCPL** function is seen followed by the previous decimal point setting.
- 3. Use the \square or \square push button to change the **Lot**; *dCPL* setting to **D**. *i*. Press **E** to accept the change.
- 4. Step through the functions by pressing and releasing **E** until the **Lot**; ; **NPL** function followed by the previous input value is seen.
- 5. Use the \square or \square push button to alter the previous input value to the new input value of 56.
- 6. Press **G**, the function **Lot**; **SCLE** will appear followed by the previous scale value.
- 7. Use the \square or \square push button to alter the previous scale value to the new scale value of 1.
- 8. Press to accept the change then either press to exit of continue pressing and releasing until the FURE End message is seen and the display returns to normal measurement mode.

Example - Rotapulse flow sensor scaling

The "Rota pulse" paddle wheel flow meter (this sensor model is commonly used as an input rate/total displays) outputs approx. 36.5 pulses per linear metre flow of liquid in a pipe. In this example we will assume that the pipe internal diameter is 50mm (25mm or 0.025m radius).

The steps to calculate the scaling of the meter for this example are as follows:

1. Calculate the area of the pipe in square metres:

Area = $\pi \times r^2 = \pi \times 0.025^2 = 0.00196 \text{m}^2$

2. Calculate the volume of a 1m length of pipe:

 $Volume = Area \times Length = 0.00196 \times 1 = 0.00196m^3$

3. For every 36.5 pulses we therefore have 0.00196 cubic metres of liquid or 1.96 litres of liquid (there are 1000 litres in one cubic metre). For a litres/sec display we could therefore have scaling factors of **FREE**; **NPE** = **3650** and **FREESELE** = **196**.

The table below shows typical rate scaling factors for this flowmeter. Note that the examples in the table can be reduced to smaller numbers as long as the ratio between the two numbers are the same. The scaling factors above are approximate and will vary depending on pipe size and installation conditions. A calibration should be carried out to determine the correct scaling for any installation where accuracy is required

Rate table for Rota Pulse flow meter with 36.5 pulses per metre flow					
Pipe dia.	Litres/sec	Litres/min	Litres/hour	m^3/hr	
25mm			ГАŁEI ЛРŁ =365	FALE: NPL =36500	
	FAFE SEFE=48	FALE SELE=295	FALE SELE=17640	FREESCLE=1764	
40mm			ГАŁE! ЛРŁ =365	ГАŁE! ЛРŁ =365	
	FALE SELE=126	FALE SELE=756	FREESELE =45360	FREESCLE=45	
50mm	ГАŁE! ЛРŁ =3650	LAFE! UDF=362	ГАŁEI ЛРŁ =365	FALE: NPL =365	
	FALE SELE=196	FREESCLE=1176	FREESCLE =70560	FREESCLE=71	
80mm		LAFE! UDF=362	LAFE! UDF=362	ГАŁE! ЛРŁ =365	
	FALE SELE =503	FALE SELE=3018	FALE SELE =181080	FREESCLE =181	
100mm		LAFE! UDF=362	ГАŁE! ЛРŁ =365	ГАŁE! ЛРŁ =365	
	FALE SELE=785	FALE SELE=4710	FALE SELE =282600	FREESCLE=281	
150mm			LAFE! UDF=362	ГАŁE! ЛРŁ =365	
	FALE SCLE=177	FALE SELE=10620	FALE SELE =637200	FREESCLE =637	

The table below shows typical total scaling factors for this flowmeter. Note that the examples in the table can be reduced to smaller numbers as long as the ratio between the two numbers are the same. The scaling factors above are approximate and will vary depending on pipe size and installation conditions. A calibration should be carried out to determine the correct scaling for any installation where accuracy is required

Total table for Rota Pulse flow meter with 36.5 pulses per metre flow				
Pipe dia.	Litres	Kilolitres or m ³		
25mm	τοτ; / ΠΡτ = 74316	Lot! $\Pi P E = 74316$		
	tot; SELE = 1000	tot; SCLE $= 1$		
40mm	ΕΟΕΙ Ι ΠΡΕ = 29029	$tot; I \Pi P t = 29029$		
	tot; SELE = 1000	tot; SCLE $= 1$		
50mm	ΕΟΙ / ΠΡΙ = 18579	$tot; ; \Pi P t = 18579$		
	tot; $SELE = 1000$	tot; SCLE $= 1$		
80mm	τοτ; ; ΠΡτ = 7257	ΕΟΕ! Ι ΠΡΕ = 7257		
	tot; SELE = 1000	tot; SCLE $= 1$		
100mm	τοτ ; ; ΠΡτ = 4645	ΕΟΕΙ Ι ΠΡΕ = 4645		
	tot; SELE = 1000	EOE! SELE $= 1$		
150mm	τοτ; ; ΠΡτ = 2064	ΕΟΕ! Ι ΠΡΕ = 2064		
	LOL! SELE $= 1000$	EOE! SELE $= 1$		

5.28 Fault finding

- Total stuck on **9999** or **999.9** etc. total needs to be reset, see *C*.; *NP*, *C*.; *N2*, *EE*; *FRP.F* **and ***CL<i>r E******E*; functions for the various methods of resetting the total.
- Display value flashing or showing **-or -** check the Lo FrE9, H, FrE9, Lo Lot; and H, Lot; function settings. If **-or -** message is seen on the rate display it means that the rate value is beyond the 4 digit display range i.e. less than **- :**999 or greater than **9999**. Check the rate scaling and adjust to suit the 4 digit display range if possible.
- Display will show rate but total stuck on **D** check the c.r 5^k function setting to see if the total is being constantly reset e.g. if c.r 5^k is set to H, the totaliser will be constantly reset unless there is a short circuit across the remote input selected for zeroing the display.
- Display not responding to input pulses for rate or total check that the input link settings and wiring match the sensor type starting at page 6.
- Display shows **\DALSERD RECS** message when trying to access functions enter setup functions via **CRL** mode (see page 15) and check the **RECS** function setting.
- Display flashes between the rate value and zero see **Lout** function.

6 Specifications

6.1 Technical specifications

Total/Rate input:	Link selectable for various sensor types, see section 3.2.	
, –	Maximum input voltage is 48VDC or RMS with appropriate link settings.	
Totaliser functions:	Scaleable up count totaliser.	
Ratemeter functions:	Scaleable rate display.	
Accuracy:	0.01% for rate indication	
Impedance:	Approx. $10k\Omega$ (depends on internal link settings)	
Max. count rate:	10kHz	
Memory retention:	Battery backed totaliser memory	
Totaliser reset:	Contact closure (or 5V control voltage) using remote input 1 or remote	
	input 2 connectors with the selected remote input function set to $2E\Gamma O$.	
Ambient temperature:	LED -10 to 50° C	
Humidity:	5 to 95% non condensing	
Display:	4 digit 20mm red led	
Power Supply:	AC 240V, 110V or 24V 50/60Hz	
	or DC isolated wide range 12 to 48V.	
	Note: supply type is factory configured.	
Transmitter supply:	24VDC unregulated 50mA max. (available on AC supplies only)	
	or 5V unregulated 20mA max.	
	DC supply models typically 15V unregulated at 25mA max.	
Power Consumption:	AC supply 4 VA max, DC supply typically 60mA at 12VDC and	
	30mA at 24VDC. Add to these figures any current taken from the	
	transmitter supply.	

6.2 Physical Characteristics

Bezel Size:	DIN 48mm x 96mm x 9mm
Case Size:	44mm x 91 mm x 120 mm behind face of panel
Panel Cut Out:	45mm x 92 mm $+1$ mm/-0mm
Connections:	Plug in screw terminals (max. 2.5 mm ² wire)
Weight:	$400~{\rm gms}$ (AC supply model) or $300{\rm gms}$ (DC supply model)

7 Guarantee and service

The product supplied with this manual is guaranteed against faulty workmanship for a period of 2 years from the date of dispatch.

Our obligation assumed under this guarantee is limited to the replacement of parts which, by our examination, are proved to be defective and have not been misused, carelessly handled, defaced or damaged due to incorrect installation. This guarantee is VOID where the unit has been opened, tampered with or if repairs have been made or attempted by anyone except an au authorised representative of the manufacturing company.

Products for attention under guarantee (unless otherwise agreed) must be returned to the manufacturer freight paid and, if accepted for free repair, will be returned to the customers address in Australia free of charge.

When returning the product for service or repair a full description of the fault and the mode of operation used when the product failed must be given. In any event the manufacturer has no other obligation or liability beyond replacement or repair of this product.

Modifications may be made to any existing or future models of the unit as it may deem necessary without incurring any obligation to incorporate such modifications in units previously sold or to which this guarantee may relate.

This document is the property of the instrument manufacturer and may not be reproduced in whole or part without the written consent of the manufacturer.

This product is designed and manufactured in Australia.